

GOVERNMENT OF ANDHRA PRADESH
ROADS & BUILDINGS DEPARTMENT

From:
Sri T.Ravindra Babu, B.Tech.,
Executive Engineer ,
(R&B) Division,
Guntur.

To:
The Correspondent,
Prodigy Vidyalay,
Ponnur Road,
Budampadu,
Guntur - 522017.

Letter No. Soundness Certificate /JTO-1 / 2020-21, Dated: 26.06.2020.

Sir,

Sub:- (R&B) Division, Guntur – Structural Soundness Certificate – School Building of Prodigy Vidyalay, Budampadu, Guntur - Report - Furnished — Regarding.

- Ref:- 1) Letter No.Nil, of the Prodigy Vidyalay, Budampadu, Guntur dated: 11.06.2020.
2) Letter No. Soundness certificate/SA/2020, Dt: 25.06.2020 of the Deputy Executive Engineer (R&B) Special Sub-Division, Guntur.

----- @@@ -----

With reference to the above, the Deputy Executive Engineer, (R&B) Special Sub-Division, Guntur has personally inspected the above said school building on 23.06.2020 which is located at Ponnur Road, Budampadu, Guntur - 522017. The existing building is RCC framed structures (G+2) constructed in the year 2018. At present, Ground floor to Second floor are utilizing for conducting class rooms.

As visual observations, it is observed that the above building is **Structurally sound as on this date.**

26/06/2020
JTO-1

26/6/2020
To

Yours sincerely

T. Ravindra Babu
Executive Engineer
(R&B) Division, Guntur
26/6/20